

Materials & Equipment for Welding with Chocolate

1. Chocolate


- Minimum four bars but extra may be needed in case of breakage
- White chocolate works best as it melts quicker, but feel free to try different chocolates to test for different strengths!

2. Heat Source

- Empty wine or milk bottle filled with hot water

3. Jig to hold the chocolate bars in place

- a shallow takeaway tray with right angles cut out



4. Weights

- Food cans/tins are a good option if actual weights are unavailable

5. 2 x plastic cups, or tin cans to balance your bridge on